

Minneapolis Inspections
 Client Services Department
 P.O. Box 18691, Minneapolis, MN 55418
 (612) 791-3223

Class 3 Arista Inspection Report
 Report: XXXX
 Client Full Name: XXXX

Date: XXXX

Line	Basic Information	Reported
000	Client Full Name	XXXX
000	Inspection Location	XXXX
000	Location Address	XXXX
000	Inspection Date & Time	XXXX
000	Contact	XXXX
000	Vehicle Identification	2008 Dodge Grand Caravan SXT
000	Engine	3.8L V6
000	Transmission	6 Speed W/AUTOSTICK & OD
000	Serial Number	1D8HN54P48B141681
000	Current Odometer Reading	52,189
000	Exterior Color	Modern Blue Pearlcoat
001	Vehicle Cleanliness	Clean, Snowy Cowl
002	Temp. During Inspection	Vehicle Inspected Indoors / 5°F
000	Weather Conditions	Sunny, Snow Covered Roads

Terms of Service

"We/our/us" means Minneapolis Inspections of Box 18691, Minneapolis, MN USA 55418. "Client/you" means a client of Minneapolis Inspections who places an order for a vehicle inspection.

Minneapolis Inspections hereby grants you a non-exclusive license to use this service for individual use of a personal nature. You may not : (1) modify, translate, or create derivative works based on the service, or permit other individuals to do so; (2) rent, lease, transfer or otherwise transfer rights to the service; (3) make copies of this report, or disseminate it any way without our express written permission.

Our vehicle inspections are prepared from visual and external checks only and are limited to the parts and/or items identified on the inspection report sheet. Vehicle inspections do not involve dismantling or disturbing of any structure, assembly, component or internal mechanism except for fluid caps.

Components which are listed on the inspection report sheet, but which are not reasonably accessible on the checked vehicle will not be inspected. In such circumstances we will be under no obligation to inspect and/or report on the component/item in question and will mark the relevant section of the report accordingly.

Our inspection can only describe and/or identify defects actually found and/or which are reasonably capable of being found upon external visual consideration of the vehicle at the time of inspection. We cannot be held and are not responsible for any latent defects, which are later discovered. In particular please note that (without limiting the possibility to such vehicles) vehicles over five years old, those that have a high mileage or which have been subjected to abnormal use may have latent defects. While such defects may, in appropriate circumstances, give rise to a claim against a vehicle supplier they fall outside the scope of our reports and our reports are provided to, and accepted by, clients on this basis.

Our inspection is based upon what is heard, felt, and what is visually seen from our operatives. Weather elements such as snow, rain and fog, lighting conditions, and the overall cleanliness of the vehicle both interior and exterior at the time of the inspection, may reduce the accuracy of the inspection resulting in possible inaccuracies. Snow build up in excess will result in the failure to check the under car systems and can make test drives difficult to detect faulty components. These conditions will be noted on the inspections report.

Any estimates for vehicle repair given by the operative in connection with an inspection reflect the subjective opinion of the operative concerned and are given solely as a matter of goodwill. Clients should not rely on such estimates in making any decision with regard to the vehicle inspected; estimates should be verified by an appropriate repairer.

Road testing is carried out within the immediate area of the vehicle inspection. If, due to circumstances outside of our reasonable control, a road test cannot be carried out at the time of inspection, the original fee shall remain fully payable. Such circumstances may include but are not limited to severe weather conditions, low fuel level except for clients receiving a Class 3 Arista Vehicle Inspection,

the vehicle is inoperable at time of inspection, or the vehicle is currently uninsured. The seller/owner is required to confirm to us that the vehicle requiring an inspection is insured and properly covered. The seller/owner is required to sign our inspection report Terms of Service to verify proper insurance coverage. The carrying out of a test drive does not mean that we have seen a valid registration or insurance certificate.

We shall not be liable for any delay in performing, or any failure to carry out an inspection to the extent that such delay or failure results from events or circumstances outside our reasonable control.

Vehicle inspections are supplied solely for the use of the client and are not for the use of, or to be relied upon by, any third party and the client shall be responsible for advising any such third party accordingly. The completed report is a copyright protected document and making copies is strictly prohibited. The information and services included in or available through the Service may include inaccuracies or typographical errors. Changes are periodically added to the information herein. Minneapolis Inspections and/or its respective suppliers may make improvements and/or changes in the Service at any time. Minneapolis Inspections does not represent or warrant that the Service will be uninterrupted or error-free, that defects will be corrected, or that the Service or the server that makes it available, are free of viruses or other harmful components. Minneapolis Inspections does not warrant or represent that the use or the results of the use of the Service or the materials made available, as part of the Service will be correct, accurate, timely, or otherwise reliable. You specifically agree that Minneapolis Inspections shall not be responsible for unauthorized access to or alteration of your data. Further, Minneapolis Inspections reserves the right to make changes to any and all parts of Minneapolis Inspections products at any time, without obligation to notify any person or entity of such changes.

Please review our complete terms of service online.

Class 3 Arista Inspection Report

Line	Component	Reported	Status	Com	Line	Component	Reported	Status	Com
003	Minor Scratches	None Noted.	[E]	[___]	036	Spare Tire Jack Hardware	Inside LR Compartment in Hatch, All in order.	[E]	[___]
004	Moderate Scratches	None Noted.	[E]	[___]	037	Headlamp Lens L	Valeo, Mopar unit. In great Shape.	[E]	[___]
005	Severe Scratches	None Noted.	[E]	[___]	038	Headlamp Lens R	Valeo, Mopar unit. In great Shape.	[E]	[___]
006	Minor Sized Dings	LF Chrome Door Guard has been creased.	[F]	[___]	039	Fog Lamp Lens L	Valeo unit. In great Shape.	[E]	[___]
007	Moderate Sized Dents	None Noted.	[E]	[___]	040	Fog Lamp Lens R	Valeo unit. In great Shape.	[E]	[___]
008	Severe Sized Dents	None Noted.	[E]	[___]	041	Tail Lamp Lens L	Mopar unit. In great Shape.	[E]	[___]
009	Accident Damage	None Noted.	[E]	[___]	042	Tail Lamp Lens R	Mopar unit. In great Shape.	[E]	[___]
010	Body Damage	None Noted.	[E]	[___]	043	Headlight Operation Low	Operating.	[E]	[___]
011	Exterior Corrosion	None Noted. Bottom of Door seams in great shape.	[E]	[___]	044	Headlight Operation High	Operating.	[E]	[___]
012	Paint Defects	None Noted.	[E]	[___]	045	Fog Light Operation	Operating.	[E]	[___]
013	Paint Condition	All exterior paint is in excellent shape. Very glossy.	[E]	[___]	046	Parking Lamp Operation	Operating.	[E]	[___]
014	Exterior Panel Alignment	RF Headlamp and Bumper alignment is poor.	[P]	[___]	047	Plate Lamp Operation	Both plate lights Operating.	[E]	[___]
015	Paint Correctness	Front and Rear bumper paint is an excellent match.	[E]	[___]	048	Tail Lamp Operation	Operating.	[E]	[___]
016	Front End Condition	Front bumper may have been replaced...	[E]	[Y]	050	Brake Lamp Operation	Operating. High mount Operating.	[E]	[___]
017	Rear End Condition	Rear bumper may have been repainted...	[E]	[Y]	051	Reverse Lamp Operation	Operating.	[E]	[___]
018	Wheel Well Condition	Excellent, clean.	[E]	[___]	052	Turn Signal Operation	Operating.	[E]	[___]
019	Cowl Condition	Snow Covered, no determination.	[E]	[___]	053	Hazard Lamp Operation	Operating.	[E]	[___]
020	Front End Bezel	Excellent shape. Chrome is in great shape.	[E]	[___]	000	Cornering Lamp Operation	N/A	[-]	[___]
021	Exterior Glass Condition	All Glass is Mopar Original.	[E]	[___]	054	Exterior Feature	Roof Rack is in Great Shape.	[E]	[___]
022	Window Molding	Excellent condition.	[E]	[___]	055	Exterior Feature	None Noted.	[E]	[___]
023	Antenna Condition	Mounted Securely.	[E]	[___]	056	Exterior Feature	None Noted.	[E]	[___]
024	Moon Roof Condition	Not Equipped Option.	[-]	[___]	057	Instrument Cluster	Operating Correctly.	[-]	[___]
025	Exterior Mirror Condition L	Secure, Excellent.	[E]	[___]	058	Message Center	Reads Odometer, Door Open. Functioning.	[E]	[___]
026	Exterior Mirror Condition R	Secure, Excellent.	[E]	[___]	059	Cluster Illumination	Excellent.	[E]	[___]
027	Wiper Blade Appearance	Original Units, LH rubber bad, Replace both fronts.	[U]	[___]	060	MIL Bulb Check	Check Engine Symbol Appears on Key On position.	[E]	[___]
028	Wiper Arm Tension	Satisfactory.	[E]	[___]	061	ABS Bulb Check	Present.	[E]	[___]
029	Fuel Door Operation	Opens, Fuel Cap in great shape.	[E]	[___]	062	SRS Bulb Check	Present.	[E]	[___]
030	Exterior Door Handles	All handles are firm and work correctly including hatch.	[E]	[___]	063	Warning Indicators	Low Tire Warning on. Tire PSI drop from Temp Drop...	[E]	[Y]
031	Door Hinges	LF, RF door hinges rusty, LF clunk when opening door.	[P]	[___]	064	Oil Pressure	No Oil Pressure gage on instrument cluster.	[-]	[___]
032	Weather Stripping	LF, RF Inside Top Rear deteriorated, wind noise LF...	[P]	[Y]	065	Speedometer Operation	Working Correctly, no glitches.	[E]	[___]
033	Hatch Operation	Automatic Feature opens/closes, works excellent.	[E]	[___]	066	Tachometer Operation	Working Correctly.	[E]	[___]
034	Hatch Condition	Very Clean.	[E]	[___]	067	Temperature Operation	Engine Temperature is at Normal mode in middle.	[E]	[___]
035	Spare Tire Condition	Underneath in middle of vehicle, appears new, nibs ok.	[E]	[___]	068	Steering Wheel	Leather material in great shape, clean and firm.	[E]	[___]

Class 3 Arista Inspection Report

Line	Component	Reported	Status	Com	Line	Component	Reported	Status	Com
069	Column Tilt	Adjuster underneath column, working correctly.	[E]	[___]	102	Rear Seat Function	All seats fold and reposition correctly.	[E]	[___]
070	Windshield Wiper Operation	LF Wiper Blade streaks, replace refills.	[P]	[___]	103	Seat Stains Front	None Noted.	[E]	[___]
071	Windshield Washer System	Front and Rear Washer pumps operating.	[E]	[___]	104	Seat Stains Rear	None Noted.	[E]	[___]
072	Horn Operation	Operating.	[E]	[___]	105	Seat Upholstery Burns	None Noted.	[E]	[___]
073	Adjustable Foot Pedals	Operating. Button on LH side of Column, Back/Aft Ok.	[E]	[___]	106	Seat Upholstery Cracking	None Noted.	[E]	[___]
074	Window Operation Down	All windows operating down.	[E]	[___]	107	Seat Upholstery Rips	None Noted.	[E]	[___]
075	Window Operation Up	All windows operating up.	[E]	[___]	108	Seat Cleanliness	Very Clean.	[E]	[___]
076	Power Door Locks	Operating.	[E]	[___]	109	Floor Mat Condition Front	Very Clean.	[E]	[___]
077	Power Mirrors	Operating.	[E]	[___]	110	Floor Mat Condition Rear	Very Clean.	[E]	[___]
078	Glove Box	Opens and closes nicely, clean. Owner's manual inside.	[E]	[___]	111	Floor Mat Condition Cargo	Not Equipped.	[-]	[___]
079	Center Console	Clean, All compartments open easily.	[E]	[___]	112	Headliner Condition	Very Clean. Overhead Compartments in good order.	[E]	[___]
080	Sun Visor	Both LH and RH lights working, clean material.	[E]	[___]	113	Rear Defrost	Operating.	[E]	[___]
081	Map Lights	Bright and Operating.	[E]	[___]	114	A/C Climate Control Unit	Full Manual Unit. Operating.	[E]	[___]
082	Courtesy Lights	No floor lights equipped.	[-]	[___]	115	Blower Motor Function	All speeds working, front and rear.	[E]	[___]
083	Moon Roof Operation	Feature not Equipped.	[-]	[___]	116	Defrost Air Function	Functioning.	[E]	[___]
084	Transmission Shifter	Excellent.	[E]	[___]	117	Vent Air Function	Functioning.	[E]	[___]
085	Interior Door Panel	All panels firm and secure. Clean.	[E]	[___]	118	Bi-Level Air Function	Functioning.	[E]	[___]
086	Cargo Area Trim Panels	LR Panel is scratched slightly.	[F]	[___]	119	Floor Air Function	Functioning.	[E]	[___]
087	Cup Holders	All cup holders in good shape. Dash unit unfolds.	[E]	[___]	120	Recirculation Door	Functioning.	[E]	[___]
088	Dash Condition	Excellent, Clean, no nicks.	[E]	[___]	121	Blend Door Operation	Functioning.	[E]	[___]
089	Power Outlet Operation	All remote power jacks operating.	[E]	[___]	122	Heat Vent Output Temp	150°F. Excellent.	[E]	[___]
090	Kick Panels	Very Clean.	[E]	[___]	123	A/C Vent Output Temp	Below Ambient Temperature to Test Correctly.	[-]	[___]
091	Thresh Plates	LF unit is dirty, wear and tear for age.	[E]	[___]	124	Dual Climate Control	Functioning correctly.	[E]	[___]
092	Heated Seat Operation	Both front seats are working.	[E]	[___]	125	Auto Climate Control	Not Equipped.	[-]	[___]
093	Carpet Stains Front	None Noted.	[E]	[___]	126	Rear Climate Control	Functioning correctly.	[E]	[___]
094	Carpet Stains Rear	None Noted.	[E]	[___]	127	Rear Blower Operation	Operating.	[E]	[___]
095	Carpet Stains Cargo	None Noted.	[E]	[___]	128	Rear Vent Operation	Operating.	[E]	[___]
096	Carpet Burns	None Noted.	[E]	[___]	129	Interior Odor	None Noted.	[E]	[___]
097	Carpet Cleanliness	Very Clean.	[E]	[___]	130	Navigational Unit	Not Equipped.	[-]	[___]
098	Protective Overlay Present	Front Present. Dealer placed.	[-]	[___]	131	Navigational Unit Disc	Not Equipped.	[-]	[___]
099	Seat Upholstery Type	Cloth.	[E]	[___]	132	Rear DVD Operation	Not Equipped.	[-]	[___]
100	Front Seat Function L	Power Function Operating.	[E]	[___]	133	Interior Feature	Front DVD Operating.	[E]	[___]
101	Front Seat Function R	Operating.	[E]	[___]	134	Interior Feature	LH,RH Automatic Sliding Doors function correctly.	[E]	[___]

Class 3 Arista Inspection Report

Line	Component	Reported	Status	Com	Line	Component	Reported	Status	Com
135	Hood Latch	Excellent Condition.	[E]	[___]	168	Drive Belt Tension	Belt Tensioner operating correctly.	[E]	[___]
136	Hood Support	Functioning Correctly.	[E]	[___]	169	Other Drive Belt Tension	N/A.	[-]	[___]
137	Engine Cleanliness	Engine has been degreased and is very clean.	[E]	[___]	170	Radiator Cap Visual	Excellent and Clean.	[E]	[___]
138	Engine Oil Level	Correct.	[E]	[___]	171	Coolant Tank Visual	Excellent.	[E]	[___]
139	Engine Oil Condition	Slightly brown but in excellent condition.	[F]	[___]	172	Coolant PSI Rating	16 PSI	[E]	[___]
140	Transmission Fluid Level	Dealer Serviced Only. No Dipstick.	[-]	[___]	173	Coolant Pressure Test	Cooling System held 16 PSI for 5 Min. No Leaks.	[E]	[___]
141	Transmission Fluid Conditio	N/A	[-]	[___]	174	A/C Refrigerant Leak Test	No Refrigerant leaks located. System in good shape.	[E]	[___]
142	Power Steering Fluid Level	Correct.	[E]	[___]	175	Engine Cover	No Cover used on this engine.	[-]	[___]
143	Power Steering Fluid Condit	Red – Excellent.	[E]	[___]	176	Fuel Rail Visual	Excellent Shape.	[E]	[___]
144	Engine Coolant Level	Correct.	[E]	[___]	177	Fuel Pressure Regulator	N/A. Located in Fuel Tank.	[-]	[___]
145	Engine Coolant Condition	Mopar Red – Excellent.	[E]	[___]	178	Fuel Injector Wiring	Excellent.	[E]	[___]
146	Engine Coolant Test	Anti-Freeze protection good to -34°F, excellent.	[E]	[___]	179	Evap. Emissions Visual	Excellent. Leak Detection Pump in good shape.	[E]	[___]
147	Brake Fluid Level	Acceptable.	[E]	[___]	180	EGR System Visual	Piping and Valve appear to be in good shape.	[E]	[___]
148	Brake Fluid Condition	Acceptable.	[E]	[___]	181	Harness Connectors	No faults found within engine compartment.	[E]	[___]
149	Engine Oil Leak	None Noted.	[E]	[___]	182	Exhaust Manifold Visual	Rusty, to be expected.	[F]	[___]
150	Engine Coolant Leak	None Noted.	[E]	[___]	183	Intake Plenum Visual	Plastic unit clean and in good shape.	[E]	[___]
151	Transmission Fluid Leak	None Noted.	[E]	[___]	184	Engine Start	Starts quickly and very quietly. Tested inside.	[E]	[___]
152	Engine Fuel Leak	None Noted.	[E]	[___]	185	Engine Idle	No abnormal faults noted.	[E]	[___]
153	Other Fluid Leak	None Noted.	[E]	[___]	186	Engine @2500RPM	Sounds great, very smooth.	[E]	[___]
154	Battery Brand / Appearance	Mopar, Original, Excellent shape. Has blanket.	[E]	[___]	187	Engine Noise	No abnormal noised noted.	[E]	[___]
155	Battery Support	Excellent.	[E]	[___]	188	Thermostat Operation	Opens around 200°F, Excellent.	[E]	[___]
156	Battery Hold Down	Excellent.	[E]	[___]	189	Main Cooling Fan Op.	Operating.	[E]	[___]
157	Battery Corrosion	None Noted.	[E]	[___]	190	Sub Cooling Fan Operation	Not Inspected.	[-]	[___]
158	Battery Terminal Connectio	Excellent.	[E]	[___]	191	A/C Compressor Operation	Engaging.	[E]	[___]
159	Upper Radiator Hose	Original. Excellent.	[E]	[___]	192	Recent Repairs Visual	None Noted.	[E]	[___]
160	Lower Radiator Hose	Original. Excellent.	[E]	[___]	193	Tire Size	P225/65R16 100S	[-]	[___]
161	Coolant Heater Hose	Original. Excellent.	[E]	[___]	194	Tire Brand	Yokohama Avid S33	[E]	[___]
162	Coolant Bypass Hose	Original. Excellent.	[E]	[___]	195	Wheel Condition	All in good shape. Mismatched Wheel Weights RH side.	[E]	[___]
163	Cooling Fan Shroud	Excellent Shape.	[E]	[___]	196	Tire Tread Depth	All at 11/32nds. Tires are new. 2/32nds is illegal.	[E]	[___]
164	A/C Condenser Fins	Excellent Shape.	[E]	[___]	197	Tire Tread Condition	Excellent.	[-]	[___]
165	Radiator Fins	Excellent Shape. Clean.	[E]	[___]	198	Estimated Tread Remaining	100%	[E]	[___]
166	Accessory Drive Belt	Original unit. No Cracking. Good Shape.	[E]	[___]	199	Tire Pressure	LF – 32, LR – 34, RR – 34, RF – 30 PSI, Should be 36.	[E]	[___]
167	Other Drive Belt	N/A. Only 1 Serpentine Belt.	[-]	[___]	200	Spare Tire Condition	Appears new, nibs on tires are still present.	[E]	[___]

Class 3 Arista Inspection Report

Line	Component	Reported	Status	Com	Line	Component	Reported	Status	Com
201	Loose Suspension Compone	None Noted.	[E]	[___]	234	Brake Drag	None Noted.	[E]	[___]
202	Loose Steering Components	None Noted.	[E]	[___]	235	Brake Pulsation	None Noted. Brakes are smooth even at 70MPH.	[E]	[___]
203	Front Brake Friction	Pads have been replaced recently 10K ago, Good units.	[E]	[___]	236	Wheel Shimmy	None Noted.	[E]	[___]
204	Front Brake Rotor Visual	Appears to be in good shape, thickened not measured.	[E]	[___]	237	Handling	Excellent.	[E]	[___]
205	Rear Brake Friction	Pads just replaced, Carquest house pads.	[E]	[___]	238	Alignment	Off Slightly. Pulls to Right even on crowned roads.	[F]	[Y]
206	Rear Brake Drum/Rotor Vis	Appears to be in good shape, thickened not measured.	[E]	[___]	239	Cruise Control Operation	Operating Correctly.	[E]	[___]
207	Drive Train Fluid Leak	None Noted.	[E]	[___]	240	GPS Navigation	N/A.	[-]	[___]
208	Brake Fluid Leak	None Noted.	[E]	[___]	241	Transmission Fluid Level	Dealer Serviced Only. No Check Point.	[-]	[___]
209	Chassis Corrosion	Fairly Clean underneath, normal climate corrosion.	[E]	[___]	242	External Fluid Leak	None Noted.	[E]	[___]
210	C.V. Half Shaft Boots L	Excellent Condition.	[E]	[___]	243	Abnormal Odor	None Noted.	[E]	[___]
211	C.V. Half Shaft Boots R	Excellent Condition.	[E]	[___]					
212	C.V. Half Shaft Boots Rear	N/A.	[-]	[___]					
213	Diagnostic System	On Board Diagnostics 2	[-]	[___]					
214	Readiness Monitors	All Completed.	[E]	[___]					
215	Monitor Not Compliant	None Noted.	[E]	[___]					
216	Current DTC	None Noted.	[E]	[___]					
217	Pending DTC	None Noted.	[E]	[___]					
218	History DTC	None Noted.	[E]	[___]					
219	Fuel Trim Calculations	0% ST/LT, Ideal Fuel Economy Noted.	[E]	[___]					
220	Engine Data	All Operations appear normal.	[E]	[___]					
221	Top Speed Achieved	70MPH	[E]	[___]					
222	Transmission Shifting	Excellent, AUTOSTICK not tested.	[E]	[___]					
223	Transmission Operation	Excellent, smooth shifting.	[E]	[___]					
224	Engine Noise	None Noted.	[E]	[___]					
225	Engine Oil Pressure	No Oil Pressure Gage Available on Cluster.	[-]	[___]					
226	Engine Coolant Temp	Normal Operating Temperature.	[E]	[___]					
227	Engine Acceleration	Excellent, Good Kickdown.	[E]	[___]					
228	Engine In Gear @ Stop	No vibration felt during this condition.	[E]	[___]					
229	Transfer Case Operation	N/A.	[-]	[___]					
230	Vibration	None Noted.	[E]	[___]					
231	Clunks	None Noted.	[E]	[___]					
232	Noises	LH Sliding Door making noise during braking, LF Door...	[F]	[Y]					
233	Brake System Operation	Operates quietly and as expected.	[E]	[___]					

Class 3 Arista Inspection Report

Line	Comments Reported
016	The front bumper cover may have been repainted. There is no paint overspray on the vehicle so it would have been painted off the vehicle. Determining this was only a matter of noticing the tool marks left on the bolt heads on the top of the bumper by the grill and also the subpar alignment by the right front headlamp. Most cheap aftermarket replacement bumpers can't match original equipment quality. There does not appear to be any damage behind the cover. The paint is a perfect match. It is possible that the bumper was scraped/gouged enough that it had to be replaced.
017	There is more conclusive evidence that the rear bumper was repainted on the vehicle. You can notice that the top threshplate bulges in the center of the bumper. Also on the LR wheel well you can notice one of the three torx screws holding the bumper to the frame has been painted blue and is sunk into the plastic. The other wheel well shows how the screws should look. Also, opening the rear hatch and looking below the right rear taillight, you will notice a torx screw that has paint defects next to the head. The screw was positioned before the paint could fully cure. The paint is a good match and the rest of the bumper is intact underneath. No damage found. A Torx screw has a star pattern and has a round head.
032	The LF and RF weather stripping on the vehicle frame side is breaking down in the top rear corner, peel back the flap and deterioration is evident. The right front door does not emit a wind noise during the test drive so, we are assuming that the LF door is bent outward at the top causing the wind noise. There are also pry marks on the inside frame at the top of the LF door. A key may have been locked in the vehicle. The door may have to be pushed/bended back into position to get a better seal.
063	The low tire pressure warning light was on during the inspection. This is most likely due to the temperature drop in the last few days causing the tire pressure to drop a few PSI. Have the tires set to 36PSI while it is cold and reset the light.
232	During the test drive at speeds about 30MPH, noise heard from the LH sliding door area emitted during braking. Sounded like a squeaking/squealing noise. Unaware of what this could be. Also the wind noise described in 032.
238	The alignment should be checked. The vehicle pulls slightly to the right even on crowned roads in the left lane.

Line	Comments Reported
000	OVERALL This is an exceptional vehicle. The interior is in excellent condition. The exterior is scratch free. The tires are new and are good quality units. The front brake pads were replaced with high end pads, which means someone might have cared. The pricing is inline with market value. There are a few things wrong that can be fixed easily but are great negotiating points. Have the LF door wind noise further inspected, take another test drive and validate that it is there, if so see if they can remedy the noise. The door may need to be bent back into position. The weather stripping is probably not the cause. Have the alignment adjusted so the vehicle does not pull to the right while your on the road. The front wiper blades should receive new refills. The tire pressures should be adjusted. All this can be done from the dealer on their end for near nothing. Just and hour of labor. If they are unwilling, negotiate the price of the vehicle down \$200.00.
000	THANK YOU! Thank you XXXX for your business. If you have any further questions about this report, please contact us.